

GigaCore
ETHERNET SWITCHES

RELEASE NOTES

VERSION 1.1.2

RELATED PRODUCTS:

GigaCore 30i

DOCUMENT INFORMATION

With the release of Firmware v1.1.2, Luminex introduces a number of bug fixes related to multicast traffic handling.

FEATURES

- No new features are introduced in this release.

BUG FIXES

- An issue was fixed to ensure that multicast data is always forwarded to the querier in the network.
- Fixed an issue where multicast router ports were incorrectly removed on topology changes.
- A bug was fixed where multicast data was not sent to querier whenever snooping was disabled.