



DOCUMENT INFORMATION

This document lists the new features and bugfixes available in the new LumiNode firmware.


NEW

DMX REDUNDANCY

- Set a DMX output port as redundant slave port. This allows you to make a redundant (ring) connection with your DMX devices.



Updated LCD, showing active redundancy.



Updated LCD, showing inactive redundancy.

ADJUSTABLE DMX BREAK TIME

- DMX break time can be adjusted via the web UI.

RELEASE NOTES LUMINODE 2.1.1

LumiNode
#WhereTraditionMeetsInnovation

BUG

FIXES

- Occasionally freezing DMX output.
- Various fixes and improvements on RDM.
- Add software debounce on contact closure.
- Fix for large size fragmented RTTrPL packages.