



Release notes.

Version 3.1.3

Related products: GigaCore 10, 14R, 16Xt, 16RFO, 26i

WWW.LUMINEX.BE

MADE IN BELGIUM



With this release, Luminex introduces a bug fix.

New Features

No new features are introduced in this release.

Bug Fixes

■ A bug that occurred since v3.1.0 was fixed where settings on SFP ports, only in combination with long (>100m) fiber cables, were not always stored correctly. This happened when toggling AVB on/off in certain groups and/or deploying configs that changed the status of the AVB setting already present in the GigaCore.



